



# 5,578 Hours

# 2,890 Landings



# Highlights

- Fully Enrolled on Programs
- Recent 120 Month Inspection
- Ka-Band Internet
- 10 Passenger Configuration
- No Damage History
- Global Vision Flight Deck Version 5
- FANS 1/A, HUD, EVS & SVS

### Airframe

TOTAL TIME SINCE NEW	5,578 Hours (as of December 2023)
TOTAL LANDINGS SINCE NEW	2,890 Landings
PROGRAM COVERAGE	Smart Parts

Left	Right
Rolls-Royce BR700-	710A2-20
5,578 Hours	5,578 Hours
2,901 Cycles	2,901 Cycles
Rolls-Royce Corporat	teCare
	Rolls-Royce BR700- 5,578 Hours 2,901 Cycles

#### APU

DESCRIPTION	Honeywell RE220 (GX)
APU TOTAL TIME SINCE NEW	6,163 Hours
PROGRAM COVERAGE	MSP

### Notable features

Crew Force Measurement System	Global Vision Flight Deck - Version 5
HUD	EVS
Ka-Band	FANS 1/A



# Interior

NUMBER OF PASSENGERS	Ten (10)
GALLEY LOCATION	Fwd
FORWARD CABIN CONFIGURATION	Four (4) Double Place Club
MID CABIN CONFIGURATION	Four (4) Place Conference Group opposite a Credenza
AFT CABIN CONFIGURATION	Two (2) Place Club opposite a Three (3) Place Divan
LAVATORY LOCATION(S)	Fwd & Aft
CREW REST	Fwd
JUMPSEAT	Yes


## Exterior

BASE PAINT COLOR(S)	White & Blue
STRIPE COLOR(S)	Grey

# Major inspection status

Inspection	Last Performed	Next Due
60 Month	Jun-2023	Feb-2028
120 Month	Jun-2023	Jul-2033

# Floorplan























#### FOR YOUR WORLD